

MALÉ DIVADLO

Elation fuze par z175 (14CH)



99



94



92

Elation fuze par z175 (14CH)



19



17



16



81

Elation fuze wash z120 (15CH)



82

85 profil

Elation fuze wash z120 (15CH)



86



38

Elation fuze par z175 (14CH)



100



98



96



39



37



36

FHR 1000



1

Elation fuze par z175 (DMX 329 - 14CH)



2

Elation fuze wash z120 (DMX 187 - 15CH)



3

Elation fuze par z175 (DMX 343 - 14CH)



4

FHR 1000



5



61



62



63 profil



64



65 profil



66



67 profil



68



69



21

FHR 1000



22

Elation fuze par z175 (DMX 401 - 14CH)



23

Elation fuze wash z120 (DMX 217 - 15CH)



24

Elation fuze par z175 (DMX 424 - 14CH)



25

FHR 1000

FHR 1000



6

Elation fuze par z175 (DMX 357 - 14CH)



7

Elation fuze wash z120 (DMX 202 - 15CH)



8

Elation fuze par z175 (DMX 371 - 14CH)



9

FHR 1000



10



201

ELATION SFX



145

ROBE



166

ROBE



202

ELATION SFX



26

FHR 1000



27

Elation fuze par z175 (DMX 438 - 14CH)



28

Elation fuze wash z120 (DMX 232 - 15CH)



29

Elation fuze par z175 (DMX 452 - 14CH)



30

FHR 1000

FHR 1000



11

Elation fuze par z175 (DMX 385 - 14CH)



12

FHR 1000



13

FHR 1000



14

FHR 1000



15



31

FHR 1000



32

Elation fuze par z175 (DMX 466 - 14CH)



33

FHR 1000



34

FHR 1000



35

FHR 1000



71



72



73 profil



74



75 profil



76



77 profil



78



79